

R.P.C. ELECTRICAL SERVICES & MAINTENANCE.

MOBILE: 07947340456.

Electrical Equipment Testing (PAT)

Original Certificate 11817

Certificate reference 113.E.D.P.

DETAILS OF CLIENT

Client/
Address:

19 Northbrook rd. Hadfield, EDIT POST
PHOTOGRAPHY

TESTING DETAILS

Test Equipment used

ETH 525

Serial Number

9125

Tested by

R.P.C.

Date

17-2-24

Retest Date

17-2-25

Number	Description	Location	Class	Visual	Earth	Insulation	Repair
1	NET GEAR 1		A	OK	OK	>20MΩ	N/A
2	NET GEAR 2		A	OK	OK	>20MΩ	N/A
3	NET GEAR 3		A	OK	OK	>20MΩ	N/A
4	NET GEAR 4		A	OK	OK	>20MΩ	N/A
5	enlinchrom Lite1		A	OK	OK	>20MΩ	N/A
6	enlinchrom Lite2		A	OK	OK	>20MΩ	N/A
7	enlinchrom Lite3		A	OK	OK	>20MΩ	N/A
8	enlinchrom Lite4		A	OK	OK	>20MΩ	N/A
9	enlinchrom Lite5		A	OK	OK	>20MΩ	N/A
10	enlinchrom Lite6		A	OK	OK	>20MΩ	N/A
11	Dell Laptop 1		A	OK	OK	>20MΩ	N/A
12	Dell Laptop 2		A	OK	OK	>20MΩ	N/A
13	Dell Laptop 3		A	OK	OK	>20MΩ	N/A
14	Dell Laptop 4		A	OK	OK	>20MΩ	N/A
15	CP3800 Printer		A	OK	OK	>20MΩ	N/A
16	CP9550 Printer		A	OK	OK	>20MΩ	N/A
17	CP9550 Printer		A	OK	OK	>20MΩ	N/A
18	Laptop Camera		A	OK	OK	>20MΩ	N/A
19	Laptop Camera		A	OK	OK	>20MΩ	N/A
20	EXT 1		A	OK	OK	>20MΩ	N/A
21	EXT 2		A	OK	OK	>20MΩ	N/A
22	EXT 3		A	OK	OK	>20MΩ	N/A
23	EXT 4		A	OK	OK	>20MΩ	N/A
24	EXT 5		A	OK	OK	>20MΩ	N/A
25	EXT 6		A	OK	OK	>20MΩ	N/A
26	EXT 7		A	OK	OK	>20MΩ	N/A
27	T.V Samsung		A	OK	OK	>20MΩ	N/A
28	T.V. Samsung		A	OK	OK	>20MΩ	N/A